## GUYMASTER Release Notes For version 5.2.1 as of July 19, 2016

1. With this release we correct an error in the tension calculations for temperature change when using the catenary cable formulation Option 1 in CABLE PROFILE. In most analyses this will have made very little difference.